Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	658	(123/41.35).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/11/08 09:13
L2	87250	(crescent or groove) near30 (arm or crank or crankshaft )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/08 09:20
L3	18	1 and 2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/08 09:16
L4	127294	(holes or nozzle or spray) near40 sides near40 (upper or top)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/08 09:18
L5	191	(123/41.37).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2004/11/08 09:18
L6	20	(1 or 5) and 4	US-PGPUB; USPAT; USOCR; EFO; JPO; DERWENT; IGM_TDB	OR	ON	2004/11/08 09:21
L7	30296	(crescent or groove or slot ) near30 (pin or arm or crank or crankshaft ) near30 bearing	UC-PGPUB; USPAT; USOCR; EPO; UPO; Dr RWENT; IE 4_TDB	OR	ON	2004/11/08 09:21
L8	28	(1 or 5) and 7	US-PGPUB; UPAT; UPOCR; E O; JPO; DEAWENT; I 1_TDB	OR	ON	2004/11/08 09:21